

Release Note

Release Date: 2010/4/29

Firmware Version:8.7.2.0-9.0.2.0

Utility Version:4.2.9.0-4.2.12.0

Test Period:2008/2/27~2009/6/18

Rev	No.	Brand Name	Description	Date	Note
1	1		First Release(319 models)	2008/2/20	
2	1	HP	CLJ 2605	2008/9/17	new
	2	HP	CLJ CP1215		new
	3	HP	CLJ CP1518ni		new
	4	HP	CLJ CP3505dn		new
	5	HP	CM1015MFP		new
	6	HP	CM1017MFP		new
	7	HP	Deskjet 3940		new
	8	HP	LaserJet P2014		new
	9	HP	LaserJet P2015		new
	10	HP	OfficeJet J6480		new
	11	HP	OfficeJet Pro K5300		new
	12	HP	Photosmart C4480		new
	13	HP	Photosmart C4580		new
	14	HP	Photosmart D7260		new
	15	HP	PSC 2110		new
	16	HP	PSC 2310		new
	17	HP	PSC 2410		new
	18	HP	PSC 2510		new
	19	SAMSUNG	CLX-2160N		new
	20	SAMSUNG	ML-1610		new
	21	SAMSUNG	ML-2010(GDI)		new
	22	Lexmark	Z603		new
	23	Lexmark	Z645		new
	24	Epson	Aculaser C3800		new
	25	Epson	Stylus C59		new
	26	Epson	Stylus CX3700		new
	27	Epson	Stylus CX4900		new
	28	Epson	Stylus CX5505		new
	29	Epson	Stylus CX6900F		new
	30	Epson	Stylus TX200		new
	31	Konica Minolta	bizhub 200		new
	32	Kyocera	FS-1030D		new
	33	Kyocera	FS-1100		new
	34	Kyocera	FS-920		new

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.

3	1	HP	CLJ CM1312nfi MFP	2010/4/29	new
	2	HP	CLJ CP2025	2010/4/29	new
	3	HP	CLJ CP3525	2010/4/29	new
	4	HP	Deskjet 930cxi	2010/4/29	new
	5	HP	Deskjet F2120	2010/4/29	new
	6	HP	LaserJet 3030	2010/4/29	update
	7	HP	LaserJet P2015D	2010/4/29	new
	8	HP	LaserJet P2055	2010/4/29	new
	9	HP	Photosmart C5380	2010/4/29	new
	10	HP	Photosmart D5460	2010/4/29	new
	11	Epson	EC-01	2010/4/29	new
	12	Epson	EPL-N2500	2010/4/29	update
	13	Epson	Stylus COLOR 750	2010/4/29	new
	14	Epson	Stylus PHOTO R1900	2010/4/29	new
	15	Epson	Stylus PHOTO R290	2010/4/29	new
	16	Canon	iP100	2010/4/29	new
	17	Canon	iP1980	2010/4/29	new
	18	Canon	iP3680	2010/4/29	new
	19	Canon	iP4680	2010/4/29	new
	20	Canon	PIXMA MP198	2010/4/29	new
	21	Canon	PIXMA MP268	2010/4/29	new
	22	Canon	PIXMA MP486	2010/4/29	new
	23	Canon	PIXMA MP545	2010/4/29	new
	24	Canon	PIXMA MP638	2010/4/29	new
	25	Konica Minolta	bizhub 210	2010/4/29	new
	26	SAMSUNG	SCX-4720F	2010/4/29	update

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

**: Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

***: Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
1	HP	Business 1000	OK	N/A		
2	HP	Business 1100d	OK	OK		
3	HP	Business 1200d	OK	OK		
4	HP	CLJ 1500L	OK	N/A		
5	HP	CLJ 1600	OK	N/A		
6	HP	CLJ 2550L	OK	OK	OK	
7	HP	CLJ 2600n	OK	N/A	OK	
8	HP	CLJ 2605	OK	N/A	OK	Vista 64 not tested yet
9	HP	CLJ 3000dn	OK	N/A	OK	
10	HP	CLJ 3500	OK	N/A		
11	HP	CLJ 3500N	OK	N/A		
12	HP	CLJ 3600	OK	N/A		
13	HP	CLJ 3600dn	OK	N/A		
14	HP	CLJ 3600n	OK	N/A		
15	HP	CLJ 3700	OK	OK		
16	HP	CLJ 4600	OK	N/A		
17	HP	CLJ 5500	N/A	OK		
18	HP	CLJ 5500dn	N/A	OK		
19	HP	CLJ CM1312nfi MFP	OK	N/A	OK	
20	HP	CLJ CP1215	NG	N/A	OK	
21	HP	CLJ CP1518ni	OK	N/A	OK	
22	HP	CLJ CP2025	OK	N/A	OK	
23	HP	CLJ CP3505	OK	N/A	OK	
24	HP	CLJ CP3505dn	OK	N/A	OK	***
25	HP	CLJ CP3525	OK	N/A	OK	
26	HP	CLJ3000dn	OK	N/A	OK	
27	HP	CM1015MFP	OK	N/A	OK	This model doesn't have Vista 64 driver
28	HP	CM1017MFP	OK	N/A	OK	This model doesn't have Vista 64 driver
29	HP	Deskjet 1120C	OK	N/A		
30	HP	Deskjet 1125C	N/A	OK		
31	HP	Deskjet 1180C	OK	OK		
32	HP	Deskjet 3325	OK	N/A		
33	HP	Deskjet 3535	OK	N/A		
34	HP	Deskjet 3550	OK	N/A		
35	HP	Deskjet 3650	OK	N/A		
36	HP	Deskjet 3820	OK	OK		
37	HP	Deskjet 3920	***OK	N/A		
38	HP	Deskjet 3940	OK	N/A	OK	
39	HP	Deskjet 450	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

***: Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
40	HP	Deskjet 5160	OK	N/A		
41	HP	Deskjet 5440	OK	N/A		
42	HP	Deskjet 5550	OK	N/A		
43	HP	DeskJet 5652	OK	OK		
44	HP	DeskJet 5740	OK	N/A		
45	HP	Deskjet 6122	OK	OK		
46	HP	DeskJet 6540	OK	N/A		
47	HP	DeskJet 6840	OK	N/A		
48	HP	Deskjet 810C	OK	OK		
49	HP	DeskJet 845C	OK	N/A	OK	
50	HP	Deskjet 880C	OK	OK		
51	HP	Deskjet 882C	OK	OK		
52	HP	Deskjet 895cxi	OK	OK	OK	
53	HP	Deskjet 920C	OK	OK		
54	HP	Deskjet 9300	OK	OK		
55	HP	Deskjet 930cxi	OK	OK	OK	
56	HP	Deskjet 960	OK	N/A		
57	HP	Deskjet 9650	OK	OK		
58	HP	Deskjet 970cxi	OK	OK	OK	
59	HP	Deskjet 980	OK	N/A		
60	HP	Deskjet 990	OK	N/A		
61	HP	Deskjet 995C	OK	N/A		
62	HP	Deskjet D2360	OK	N/A		
63	HP	Deskjet D2460	OK	N/A	OK	
64	HP	Deskjet F2120	OK	N/A	OK	
65	HP	Deskjet F2180	OK	N/A	OK	
66	HP	Deskjet F380	OK	N/A	OK	
67	HP	Deskjet F4185	OK	N/A	OK	OK
68	HP	DeskJet845C	OK	N/A	OK	
69	HP	LaserJet 1012	OK	N/A		
70	HP	LaserJet 1015	OK	N/A		
71	HP	LaserJet 1200	OK	OK		
72	HP	LaserJet 1220	OK	OK		
73	HP	LaserJet 1300	OK	OK		
74	HP	LaserJet 1320	OK	OK		
75	HP	LaserJet 2300	OK	N/A		
76	HP	LaserJet 2300L	OK	OK		
77	HP	LaserJet 2420	OK	OK		
78	HP	LaserJet 2420dn	OK	OK		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
79	HP	LaserJet 2605	OK	N/A		
80	HP	LaserJet 2700	OK	N/A		
81	HP	LaserJet 3015	OK	OK		
82	HP	LaserJet 3020	OK	OK	OK	
83	HP	LaserJet 3030	OK	OK	OK	
84	HP	LaserJet 3050	OK	N/A		
85	HP	LaserJet 3050z	OK	N/A	N/A	
86	HP	LaserJet 3052	OK	N/A		
87	HP	LaserJet 3055	OK	N/A		
88	HP	LaserJet 3200	OK	N/A		
89	HP	LaserJet 3300	OK	OK		
90	HP	LaserJet 3330mfp	OK	OK		
91	HP	LaserJet 3380	OK	OK	N/A	
92	HP	LaserJet 3390	OK	N/A		
93	HP	LaserJet 3392	OK	N/A		
94	HP	LaserJet 4200L	N/A	OK		
95	HP	LaserJet 4350	OK	OK		
96	HP	LaserJet 4650	OK	N/A		
97	HP	LaserJet 5100LE	N/A	OK		
98	HP	LaserJet 5100SE	N/A	OK		
99	HP	LaserJet 5200L	OK	OK		
100	HP	LaserJet 5200n	OK	OK	OK	
101	HP	LaserJet M1005MFP	OK	N/A	OK	
102	HP	LaserJet P2014	OK	N/A	OK	***
103	HP	LaserJet P2015	OK	N/A	OK	***
104	HP	LaserJet P2015D	OK	N/A	OK	
105	HP	LaserJet P2055	OK	N/A	OK	
106	HP	OfficeJet 4110	OK	N/A		
107	HP	OfficeJet 4255	OK	N/A	OK	
108	HP	OfficeJet 4355	OK	N/A	OK	
109	HP	OfficeJet 5110	OK	OK		
110	HP	OfficeJet 5510	OK	N/A		
111	HP	OfficeJet 5610	OK	N/A	OK	
112	HP	OfficeJet 6110	OK	N/A		
113	HP	OfficeJet 6210	OK	N/A		
114	HP	OfficeJet 6310	OK	N/A	OK	
115	HP	OfficeJet 7130	OK	N/A		
116	HP	OfficeJet 7210	OK	N/A		
117	HP	OfficeJet 7410	OK	N/A	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
118	HP	OfficeJet 9100	OK	N/A		
119	HP	OfficeJet 9110	OK	OK		
120	HP	OfficeJet 9120	OK	OK		
121	HP	OfficeJet 9130	OK	OK		
122	HP	OfficeJet J5780	OK	N/A	OK	
123	HP	OfficeJet J6480	OK	N/A	OK	built in network function
124	HP	OfficeJet K7100	OK	--	OK	
125	HP	OfficeJet K8600	OK	N/A	OK	
126	HP	OfficeJet Pro K5300	OK	N/A	OK	
127	HP	OfficeJet Pro K5400	OK	N/A		
128	HP	OfficeJet Pro K5400dn	OK	N/A	OK	
129	HP	OfficeJet Pro K550	OK	N/A	OK	
130	HP	OfficeJet Pro K850	OK	OK		
131	HP	OfficeJet Pro L7380	OK	N/A	OK	
132	HP	OfficeJet Pro L7580	Ok	N/A	OK	
133	HP	OfficeJet V40	OK	N/A		
134	HP	Photosmart 145	OK	N/A		
135	HP	Photosmart 245	OK	N/A		
136	HP	Photosmart 2575	OK	N/A	OK	
137	HP	Photosmart 2610	OK	N/A	OK	
138	HP	Photosmart 2710	OK	N/A		
139	HP	Photosmart 3110	OK	N/A		
140	HP	Photosmart 325	OK	N/A		
141	HP	Photosmart 3310	OK	N/A		
142	HP	Photosmart 375	OK	N/A		
143	HP	Photosmart 475	OK	N/A		
144	HP	Photosmart 7260	OK	N/A		
145	HP	Photosmart 7450	OK	N/A		
146	HP	Photosmart 7550	OK	N/A		
147	HP	Photosmart 7660	OK	N/A		
148	HP	Photosmart 7760	OK	N/A		
149	HP	Photosmart 7830	OK	N/A		
150	HP	Photosmart 7960	OK	N/A		
151	HP	Photosmart 8030	OK	N/A	OK	
152	HP	Photosmart 8230	OK	N/A	OK	
153	HP	Photosmart 8250	OK	N/A		
154	HP	Photosmart 8450	OK	N/A		
155	HP	Photosmart 8750	OK	N/A		
156	HP	Photosmart A526	OK	N/A	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
157	HP	Photosmart C3180	OK	N/A	OK	
158	HP	Photosmart C4180	OK	N/A		
159	HP	Photosmart C4280	OK	N/A	OK	
160	HP	Photosmart C4385	OK	N/A	OK	
161	HP	Photosmart C4480	OK	N/A	OK	no 2000 driver
162	HP	Photosmart C4580	OK	N/A	OK	no 2000 driver
163	HP	Photosmart C5180	OK	N/A	OK	
164	HP	Photosmart C5380	OK	N/A	OK	no 2000 driver
165	HP	Photosmart C6180	OK	N/A	OK	
166	HP	Photosmart C6280	OK	N/A	Ok	
167	HP	Photosmart C7180	Ok	N/A	OK	
168	HP	Photosmart C7280	OK	N/A	OK	
169	HP	Photosmart D5160	OK	N/A	OK	
170	HP	Photosmart D5460	OK	N/A	OK	no 2000 driver
171	HP	Photosmart D7160	OK	N/A		
172	HP	Photosmart D7260	OK	N/A	OK	built in network function
173	HP	Photosmart D7360	OK	N/A	OK	
174	HP	PSC 1110	OK	N/A		
175	HP	PSC 1210	OK	N/A	OK	
176	HP	PSC 1315	OK	N/A	OK	
177	HP	PSC 1350	OK	N/A		
178	HP	PSC 1410	OK	N/A	OK	
179	HP	PSC 1510	OK	N/A	OK	
180	HP	PSC 1610	OK	N/A	OK	
181	HP	PSC 2110	OK	N/A	OK	
182	HP	PSC 2210	OK	N/A		
183	HP	PSC 2310	OK	N/A	OK	
184	HP	PSC 2355	OK	N/A	OK	
185	HP	PSC 2410	OK	N/A	OK	
186	HP	PSC 2510	OK	N/A	OK	
187	HP	PSC 4110	OK	N/A		
188	HP	PSC 750	OK	N/A		
189	Epson	Aculaser C1900	OK	OK		
190	Epson	Aculaser C3800	OK	OK	OK	
191	Epson	Aculaser C4000	OK	OK		
192	Epson	Aculaser C4100	OK	OK		
193	Epson	Aculaser C8600	OK	OK		
194	Epson	DLQ-3500C	OK	OK		
195	Epson	EC-01	OK	N/A	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
196	Epson	EPL-5900L	OK	OK	OK(Vista32)	***No Vista 64
197	Epson	EPL-6100	OK	OK		
198	Epson	EPL-6200	OK	OK	OK(Vista32)	No Vista 64
199	Epson	EPL-N2500	OK	OK	OK	
200	Epson	EPL-N2750	N/A	OK		
201	Epson	EPL-N3000	OK	OK	OK	
202	Epson	LQ-2080C	N/A	OK		
203	Epson	LQ-300+	N/A	OK		
204	Epson	LQ-300+II	OK	OK	OK(Vista32)	No Vista64
205	Epson	LQ-680C	N/A	OK	N/A	
206	Epson	PictureMate	OK	N/A		
207	Epson	Stylus C110	OK	N/A	OK	
208	Epson	Stylus C4100	OK	N/A	OK	
209	Epson	Stylus C43UX	OK	N/A		
210	Epson	Stylus C45	OK	N/A	OK	
211	Epson	Stylus C59	OK	N/A	OK(Vista32)	no Vista64
212	Epson	Stylus C63	OK	N/A		
213	Epson	Stylus C67	OK	N/A		
214	Epson	Stylus C83	OK	N/A		
215	Epson	Stylus C88	OK	N/A		
216	Epson	Stylus C90	OK	N/A	OK	
217	Epson	Stylus COLOR 1160	OK	N/A		
218	Epson	Stylus COLOR 740	OK	OK	OK	
219	Epson	Stylus COLOR 750	OK	OK	OK	
220	Epson	Stylus COLOR 880	OK	Not Test		
221	Epson	Stylus COLOR 900	OK	Not Test		
222	Epson	Stylus CX1500	OK	N/A		
223	Epson	Stylus CX3100	OK	N/A		
224	Epson	Stylus CX3700	OK	N/A	OK	
225	Epson	Stylus CX3900	OK	N/A	OK	
226	Epson	Stylus CX4100	OK	N/A	OK	
227	Epson	Stylus CX4700	OK	N/A	OK	
228	Epson	Stylus CX4900	OK	N/A	OK	
229	Epson	Stylus CX5100	OK	N/A		
230	Epson	Stylus CX5300	OK	N/A		
231	Epson	Stylus CX5500	OK	N/A	OK	
232	Epson	Stylus CX5505	OK	N/A	OK	
233	Epson	Stylus CX5700F	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
234	Epson	Stylus CX5900	OK	N/A	OK	
235	Epson	Stylus CX6900F	OK	N/A	OK	
236	Epson	Stylus CX7300	OK	N/A	OK	
237	Epson	Stylus CX8300	OK	N/A	OK	
238	Epson	Stylus CX9300F	OK	N/A	OK	
239	Epson	Stylus CX9400F	OK	N/A	OK	
240	Epson	Stylus PHOTO 1390	OK	N/A	OK	
241	Epson	Stylus PHOTO 2100	OK	OK		
242	Epson	Stylus PHOTO 830U	OK	N/A		
243	Epson	Stylus PHOTO 935	OK	N/A		
244	Epson	Stylus PHOTO EX3	OK	OK	OK	
245	Epson	Stylus PHOTO R1900	OK	N/A	OK	
246	Epson	Stylus PHOTO R210	OK	N/A		
247	Epson	Stylus PHOTO R230	OK	N/A		
248	Epson	Stylus PHOTO R270	OK	N/A	--	
249	Epson	Stylus PHOTO R290	OK	N/A	OK	
250	Epson	Stylus PHOTO R340	OK	N/A		
251	Epson	Stylus PHOTO R350	OK	N/A		
252	Epson	Stylus PHOTO RX430	OK	N/A		
253	Epson	Stylus PHOTO RX510	OK	N/A		
254	Epson	Stylus PHOTO RX520	OK	N/A		
255	Epson	Stylus PHOTO RX530	OK	N/A	OK	
256	Epson	Stylus PHOTO RX590	OK	N/A	OK	
257	Epson	Stylus PHOTO RX630	OK	N/A		
258	Epson	Stylus PHOTO RX650	OK	N/A	OK	
259	Epson	Stylus PHOTO750	OK	OK	OK	
260	Epson	Stylus TX200	OK	N/A	OK	
261	Canon	C350	OK	N/A		
262	Canon	i255	OK	N/A		
263	Canon	i320	OK	N/A		
264	Canon	i355	OK	N/A		
265	Canon	i450	OK	N/A		
266	Canon	i455	OK	N/A		
267	Canon	i475D	OK	N/A		
268	Canon	i550	OK	N/A		
269	Canon	i560	OK	OK		
270	Canon	i6100	OK	OK		
271	Canon	i6500	OK	OK		
272	Canon	i850	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
273	Canon	i865	OK	OK		
274	Canon	i9100	OK	N/A		
275	Canon	i9950D	OK	N/A		
276	Canon	iC D380	OK	N/A		
277	Canon	iP100	OK	N/A	OK	
278	Canon	iP1000	OK	N/A		
279	Canon	iP1200	OK	N/A	OK	
280	Canon	iP1500	OK	N/A		
281	Canon	iP1880	OK	N/A	OK	
282	Canon	iP1980	OK	N/A	OK	
283	Canon	iP2000	OK	N/A		
284	Canon	iP3000	OK	N/A		
285	Canon	iP3300	OK	N/A	OK	
286	Canon	iP3500	OK	N/A	OK	
287	Canon	iP3680	OK	N/A	OK	
288	Canon	iP4000	OK	OK		
289	Canon	iP4200	OK	N/A	OK	
290	Canon	iP4300	OK	N/A	OK	
291	Canon	iP4500	OK	N/A	OK	
292	Canon	iP4680	OK	N/A	OK	
293	Canon	iP5000	OK	N/A		
294	Canon	iP6000D	OK	N/A		
295	Canon	iP8500D	OK	N/A		
296	Canon	iP90	OK	N/A		
297	Canon	iR 2010	OK	OK		
298	Canon	iR 6000	N/A	OK		
299	Canon	iR 8500	N/A	OK		
300	Canon	iX4000	OK	N/A	OK	
301	Canon	iX5000	OK	N/A		
302	Canon	PIXMA MP110	OK	N/A		
303	Canon	PIXMA MP130	OK	N/A	OK	
304	Canon	PIXMA MP145	OK	N/A	OK	
305	Canon	PIXMA MP150	OK	N/A		
306	Canon	PIXMA MP160	OK	N/A		
307	Canon	PIXMA MP170	OK	N/A		
308	Canon	PIXMA MP180	OK	N/A		
309	Canon	PIXMA MP198	OK	N/A	OK	
310	Canon	PIXMA MP268	OK	N/A	OK	
311	Canon	PIXMA MP450	OK	N/A	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
312	Canon	PIXMA MP486	OK	N/A	OK	
313	Canon	PIXMA MP510	OK	N/A		
314	Canon	PIXMA MP520	OK	N/A	OK	
315	Canon	PIXMA MP545	OK	N/A	OK	
316	Canon	PIXMA MP638	OK	N/A	OK	
317	Canon	PIXMA MP700	OK	N/A		
318	Canon	PIXMA MP730	OK	N/A		
319	Canon	PIXMA MP780	OK	N/A		
320	Canon	Pro 9000	OK	N/A		
321	Canon	Pro9000	OK	N/A	OK	
322	Canon	S200SPx	OK	N/A		
323	Lexmark	C510	OK	OK		
324	Lexmark	E120	OK	N/A		
325	Lexmark	E230	OK	OK		
326	Lexmark	P4350	OK	N/A	--	No Vista
327	Lexmark	X6170	OK	N/A	OK(Vista 64)	No Vista32
328	Lexmark	Z1420	OK	N/A	OK	
329	Lexmark	Z603	OK	N/A	OK	**
330	Lexmark	Z615	OK	N/A		**
331	Lexmark	Z645	OK	N/A	OK	**
332	Lexmark	Z705	OK	N/A		**
333	Lexmark	Z810	OK	N/A		**
334	Lexmark	Z816	OK	N/A		**
335	Lexmark	Z818	OK	N/A	OK(Vista 32)	**No Vista 64
336	Konica Minolta	bizhub 200	OK	N/A	OK(Vista 32)	No Vista64
337	Konica Minolta	bizhub 210	OK	N/A	OK(Vista 32)	No Vista64
338	Konica Minolta	Magicolor 2480MF	OK	N/A	OK(Vista 32)	***No Vista64
339	Konica Minolta	Magicolor 5550	OK	N/A		
340	Konica Minolta	Magicolor 5570	OK	N/A		
341	Dell	944	OK	N/A		
342	Dell	Mono LaserMFP1125	OK	N/A		*** No Win2000
343	Brother	HL-2070	OK	N/A		
344	Brother	HL-5240	OK	N/A		
345	Brother	MFC-210C	OK	N/A		
346	Brother	MFC-215C	OK	N/A		
347	Brother	MFC-2820	OK	N/A		
348	Brother	MFC-3240C	OK	N/A		
349	Brother	MFC-420CN	OK	N/A		
350	Brother	MFC-425CN	OK	N/A		

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

***: Users have to close bi-directional.



Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
351	Brother	MFC-4800J	OK	N/A		
352	Brother	MFC-7420	OK	N/A		
353	Brother	MFC-7820N	OK	N/A		
354	Brother	MFC-8840D	OK	N/A		
355	Kyocera	FS-1030D	OK	OK	OK	
356	Kyocera	FS-1100	OK	N/A	OK	
357	Kyocera	FS-920	OK	OK	OK	
358	SAMSUNG	CLX-2160N	OK	N/A	OK	
359	SAMSUNG	ML-1520LP	OK	N/A		
360	SAMSUNG	ML-1610	OK	N/A	OK	
361	SAMSUNG	ML-1740	OK	OK		
362	SAMSUNG	ML-2010(GDI)	OK	N/A	OK	
363	SAMSUNG	SCX-4100	OK	OK		
364	SAMSUNG	SCX-4200	OK	OK		
365	SAMSUNG	SCX-4521F	OK	OK	OK	
366	SAMSUNG	SCX-4720F	OK	OK	OK	
367	SAMSUNG	SF-565P	OK	OK	OK	

N/A: means the MFP doesn't support the function.

-- : means the function is not tested.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

*** : Users have to close bi-directional.